



DONALD L. WOLFE, Director

COUNTY OF LOS ANGELES

DEPARTMENT OF PUBLIC WORKS

"To Enrich Lives Through Effective and Caring Service"

BUILDING AND SAFETY DIVISION
PROPERTY REHABILITATION SECTION
FIRESTONE OFFICE
7807 S. COMPTON AVE.
LOS ANGELES, CALIFORNIA 90001
Telephone: 323-586-6541
Fax: 323-586-6526
<http://www.ladpw.org>

ADDRESS ALL CORRESPONDENCE TO:
7807 S. COMPTON AVE.
LOS ANGELES, CALIFORNIA 90001

IN REPLY PLEASE
REFER TO FILE:

INFORMAL NOTICE **SUBSTANDARD CONDITIONS**

February 8, 2008

Roberto And Pineda
1216 E 69th St
Los Angeles, CA 90001-0000

Property Address: **1216 E 69TH ST, LOS ANGELES**
AIN: **6010-012-006**

The following substandard property or substandard building(s) or both were observed on this property:

- Overgrown vegetation, weeds, and debris.
- Broken or discarded household furniture or household equipment or both in yard areas for unreasonable periods.
- Miscellaneous articles of personal property about the premises.
- Trash, junk, and debris about the premises.
- Garbage cans stored in the front or side yards and visible from a public street.

This "INFORMAL NOTICE" is provided to allow you to abate (correct) the noted substandard conditions by **February 23, 2008**. When you ***have abated*** (corrected) the substandard conditions, please contact your inspector so the work done may be inspected and the Code enforcement action closed by the deadline date.

If the substandard conditions are ***not abated***, the Department of Public Works will initiate formal Code enforcement action and you will receive a bill in the amount of **\$415.80** for the County's cost to conduct investigation and processing. If the bill is not paid, all of this agency's actual cost, plus an additional **\$201.20**, shall be placed as a special assessment on the tax bill pursuant to Section 25845 of the Government Code.

It is in your financial interest to correct the violations as soon as possible. Any further information may be obtained by contacting the undersigned.

Robert Gomez
Contract Building Inspector
323-586-6541

Date Posted 2-8-08 By Robert Gomez





DEPARTMENT OF PUBLIC WORKS
BUILDING AND SAFETY DIVISION
REHABILITATION SECTION
900 South Fremont Avenue
Alhambra, CA 91803
(626) 458-3193

JOB ADDRESS: 6010-012-006
1216 E. 69TH ST. Los Angeles

THIS PROPERTY IS BEING INVESTIGATED
TO DETERMINE SUBSTANDARD CONDITIONS
UNTIL A COPY OF OUR LETTER TO THE
OWNER IS ATTACHED TO THIS CARD,
DO NOT ISSUE ANY PERMITS
(EXCEPT FOR DEMOLITION) WITHOUT
FIRST CHECKING WITH THE UNDERSIGNED.

DATE: February 8, 2008
INSPECTOR: Robert Gomez